

## **Marketing Bulletin - Penberthy Sight Flow Indicators and Sight Windows**

During ongoing product design reviews, Penberthy's engineering staff discovered the need to update the cover and/or window thickness on some SF / SW models.

The update is mandated by the changes to and material additions to the ASME 'm' and 'y' gasket factors for the variety of gasketing materials available. These changes will allow free interchange of all known gasketing materials. The SFI bodies were also reviewed and are in full compliance with ANSI/ASME B16.34.

The result is an increase in glass and/or cover thickness for some units resulting in an overall increase in the face to face dimension across the sight flow windows. There is no change to any flange face to face or threaded end dimensions, therefore pipe fitting interchangeability with existing units is not an issue.

There could be a difference when ordering replacement glass or covers so it is important when ordering these items that you let us know the original order number or ship date. In order to accommodate the correct spare part, we may have to provide longer bolting.

You should not be concerned about the rating of any product shipped before this change as long as the gasketing is replaced by the same type as originally supplied.

If you have any questions or concerns please do not hesitate to call either myself or the Sight Flow team here at Penberthy.

Len Wright  
Sales Manager  
Tyco Valve and Controls, Prophetstown.  
815 537 2311 Ext. 125  
Email [lwright@tycovalves.com](mailto:lwright@tycovalves.com)

July 19, 2002